

Working Example


1. Loading workpiece.




2. Connect the electric cable to the chuck.



3. Switch ON for magnetic power.



4. Take OFF the electric cable.



5. Surface machining.



6. Side machining.



7. Rotate angle and keep to machining.



8. Finish works and connect the cable for switch OFF.

